




Canvas cutting diagram









Lining cutting diagram





Interfacing diagram





Step 3







Step 4




Step 5




Step 6









Step 7





Step 8




Step 9





Step 10





Step 11





Step 12





Step 13








Step 14



Step 15



Step 16

